



## Federal Aviation Administration

---

---

# SAFETY ALERT

Date: October 21, 2013

To: Users of the U.S. Terminal Procedure Publication (TPP) East Central (EC) Volume 2 of 3, and digital-TPP (d-TPP).

From: Aeronautical Navigation Products (AeroNav Products).

Subject: Port Columbus International (CMH) – Incorrect Hot Spot description.

---

---

**The October 17, 2013 edition of the U.S. Terminal Procedure Publication (TPP) East Central (EC) Volume 2 of 3, and the digital-TPP** contain incorrect Hot Spot descriptions for Port Columbus International airport (CMH), OH.

Only one Hot Spot exists at Port Columbus International airport. The correct description is as follows:

**HS-1      Area not visible from the twr.**

This description supersedes the Hot Spot descriptions found on page P-1 of the U.S. TPP EC volume 2 of 3 and digital-TPP. The Airport Diagram (AD) for Port Columbus International airport (CMH) in the U.S. TPP is correct.

The revised Hot Spot description can be accessed at the following link:

<http://aeronav.faa.gov/d-tpp/1311/EC2HOTSPOT.PDF>

Published by the  
U.S. DEPARTMENT OF TRANSPORTATION  
Federal Aviation Administration