



## Federal Aviation Administration

---

---

# SAFETY ALERT

Date: December 6, 2013

To: Users of the Terminal Procedures Publication South East Volume 3 (SE-3) and Users of the digital-Terminal Procedures Publication (d-TPP) DVD.

From: Aeronautical Navigation Products (AeroNav Products)

Subject: Correction to the TPP SE-3 and the d-TPP DVD for the December 12, 2013 Effective Date, Volume 1313 for Miami Intl (MIA), Miami, FL Missing Hotspot Information

---

---

The December 12, 2013 edition of the U.S. Terminal Procedure Publication (TPP) South East (SE) Volume 3 of 4, and the digital-TPP Volume 1313 are missing Hot Spot descriptions for Miami Intl, Miami, FL on Hot Spot pages P1 and/or P2.

The following five Hot Spots exist at Miami Intl airport:

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
MIAMI, FL		
MIAMI INTL (MIA)	HS 1	Short twy risk.
	HS 2	Short twy risk.
	HS 3	Rwy 27 and Rwy 30 wrong rwy departure risk.
	HS 4	Short twy between rwys.
	HS 5	Multiple rwy ends close together. Some hold lines dependent upon rwy in use.

To obtain the correct pdf file, you can download them from the AeroNav web site at: <http://aeronav.faa.gov/d-tpp/1313/SE3HOTSPOT.PDF>

PLEASE NOTE. If you access d-TPP by running directly from the DVD, the missing information will not automatically be added. However, if you install the d-TPP onto your computer, the correct SE3HOTSPOT file can be copied into the "published\_pdfs" folder of your d-TPP copy and the program will access them normally.

For technical assistance, please call 1 (800) 626-3677 or e-mail: [9-AMC-Aerochart@FAA.gov](mailto:9-AMC-Aerochart@FAA.gov)