


Flight Procedures Cover Page	Task Action: Amendment	Task Type: IAP	Estimated Chart Date: 04/23/2020	APWS Task ID: 306DE5207FE442BEAB8EA74D50D4E11D	APWS Request ID: C8518230C6E14F69AD41A7AECB8A9F92
Procedure: RNAV (GPS) RWY 14 AMDT 1A		Enroute: NO	Specialist: Sickels, Dale		Agreement Number:
Airport ID: KDIK	Airport Name: DICKINSON - THEODORE ROOSEVELT RGNL		Airport City: DICKINSON		State: ND
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<div>Procedure Comments: PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.</div> <div>P-NOTAM.</div> <div>CIRCLING ICON.</div> <div>ACTIVE DATA USED.</div> <div>CONTACT DAVID DANNER, AJV-A421, 405-954-5077.</div> <div>QUALITY 15 CHECKED</div> <div>QUALITY 10 CHECKED</div>					

RNAV (GPS) RWY 14

MISSED APPROACH: Climb to 5000
direct LUGI and hold.

UNICOM
123.0 (CTAF) **L**



46°48'N-102°48'W

DICKINSON-THEODORE ROOSEVELT RGNL (DIK)

RNAV (GPS) RWY 14

