HONIE NINE ARRIVAL (RNAV)



ARRIVAL ROUTE DESCRIPTION

CROSS CITY TRANSITION (CTY.HONIE9):
GREENE COUNTY TRANSITION (GCV.HONIE9):
MERIDIAN TRANSITION (MEI.HONIE9):
MONTGOMERY TRANSITION (MGM.HONIE9):
SEMINOLE TRANSITION (SZW.HONIE9):

From over LGC VORTAC on track 053° to HONIE, then on track 053° to TIROE, then on track 053° to WOLMN, thence on assigned runway transition.

Landing West Rwy 28, 27L/R: From over WOLMN on track 053° to FOGOG, then on track 095° to BOJAA, then on track 095° to HEDEG, then on track 095° to SOFOR, then on heading 095°. Expect radar vectors to final approach course.

Landing West Rwy 26L/R: From over WOLMN on track 028° to NOFIV, then on track 095° to FANEW, then on track 095° to HAVAD, then on track 094° to IGEBE, then on heading 094°. Expect radar vectors to final approach course.

Landing East Rwy 8L/R, 9L/R, 10: From over WOLMN on track 053° to FOGOG, then on track 095° to BOJAA, then on track 095° to HEDEG, then on track 095° to SOFOR, then on heading 095°. Expect radar vectors to final approach course after WOLMN.

LOST COMMUNICATIONS:

EAST OPERATIONS: At WOLMN track to HESPI, fly heading 360°, maintain 4000; intercept and execute ILS or LOC Rwy 10 approach. If unable, proceed to ATL VORTAC and hold, maintain 4000.

WEST OPERATIONS: At SOFOR fly heading 360°, maintain 4000; intercept and execute ILS or LOC Rwy 28 approach. If unable, proceed to ATL VORTAC and hold, maintain 4000.

PROTOTYPE:
NOT FOR
NAVIGATION