DAVIS MONTHAN TWO DEPARTURE (DMA2•DMA)



During RADAR operations aircraft will receive RADAR vectors to appropriate transition.

DME REQUIRED

SW-4, 20 JUN 2019 to 18 JUL 2019