ANCHORAGE, ALASKA

TACAN Z RWY 16

TACAN EDF Chan 81	APCH CRS 133°	Rwy ldg 7493 TDZE 213 Arpt Elev 213	AL-1196 [USAF]	ELMENDORF AFB (PAED)

* Circling not authorized SW of Rwys 6 and 34.

MISSED APPROACH: Climbing left turn to 6000 via EDF TACAN R-313 to LUBEE and hold. Continue climb-in-hold to 6000.

ATIS *	ANCHORAGE APP CON	ELMENDORF TOWER	GND CON	CLNC DEL	PAR
124.3 273.5	North 118.6 290.5 South 123.8 259.3	127.2 352.05	121.8 275.8	128.8 306.925	

Visibility reduction by Helicopters NA.

R-313

EDF 25

Max holding alt 8000
Min holding alt 6000

133°

313°

(IAF) LUBEE EDF 17

133°

CAUTION: Terrain rises rapidly to the S and E.
-Winds in vicinity of higher terrain may produce severe turbulence.
-Uncontrolled light aircraft operations in the vicinity of Six-mile lake at or below 600.

CEGEN EDF 12

963

R-2203B

BETUN EDF 6

R-2203C

R-2203A

564

ELMENDORF Chan 81 EDF

MERRILL FLD

ANCHORAGE INTL

MSA EDF 25 NM

153°

9000

2800

273°

003°

8500

EMERG SAFE ALT 100 NM 15,200

LUBEE R-313 17

VGSI and descent angles not coincident (VGSI angle 3.00°/TCH 47).

6000

EDF R-313

LUBEE

CEGEN 12

6000

133°

BETUN 6

3900

2

HADUL 1

TACAN

2000

3.08°

TCH 56

5 NM

0.3 NM

ELEV 213	TDZE 213

428

133° to TACAN

499

9L

0.4% DOWN

A1

24

10,000 × 200

245

0.3% UP

TWR

7493 × 150

34

Drops off

TDZL/CL Rwy 6
HIRL all Rwy

CATEGORY	A	B	C	D
S-16	700-1 487 (500-1)		700-1 3/8 487 (500-1 3/8)	
CIRCLING*	800-1 587 (600-1)		920-2 707 (800-2)	920-2 1/4 707 (800-2 1/4)

AK, 10 SEP 2020 to 05 NOV 2020

AK, 10 SEP 2020 to 05 NOV 2020