AL-511 [USN]

DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RWY 3L/R: Climbing left turn to intercept BZA VORTAC R-304 to CARGO. Cross SALUD at or above 3600. Thence...

TAKE-OFF RWY 8: Climb to 1000, then climbing left turn direct BZA VORTAC. Then via BZA R-304 to CARGO. Do not exceed 270 KIAS to 1000. Cross SALUD at or above 3600. Thence...

TAKE-OFF RWY 17: Climb to 1000, then climbing left turn direct BZA VORTAC. Then, via BZA R-304 to CARGO. Cross SALUD at or above 3600. Thence...

TAKE-OFF RWY 21L/R, 26: Climb to 800, then climbing left turn direct BZA VORTAC. Then via BZA R-304 to CARGO. Cross SALUD at or above 3600. Thence...

TAKE-OFF RWY 35: Climb direct BZA VORTAC, then via BZA R-304 to CARGO. Cross BZA VORTAC at or below 14,000. Do not exceed 300 KIAS in turn at BZA VORTAC. Cross SALUD at or above 3600. Thence...

BARD TRANSITION (CARGO1•BZA): At CARGO, turn left to intercept BZA VORTAC R-285 to BZA.

BLYTHE TRANSITION (CARGO1•BLH): At CARGO, turn right to intercept BLH VORTAC R-175 to BLH.

IMPERIAL TRANSITION (CARGO1•IPL): At CARGO, turn left to intercept IPL VORTAC R-050 to IPL.

Then via assigned route. Maintain assigned altitude. Expect clearance to filed altitude 10 minutes after departure.