SE-4, 29 OCT 2026 to 26 NOV 2026

ARRIVAL ROUTE DESCRIPTION

From CHPPR on track 147° to MRCHH.
LANDING RWYS 26L/R: From MRCHH on track 147° to HIDRO, then on track 147° to RAIIN, then on track 095° to KLOWD, then on track 095° to SWEPT, then on track 095° to KYMMY, then on track 095° to KEAVY, then on track 095°. Expect RADAR vectors to final approach course.
LANDING RWYS 27L/R, 28: From MRCHH on track 147° to HIDRO, then on track 163° to EAGYL, then on track 095° to SHURT, then on track 095° to FOGER, then on track 095° to HITTT, then on track 095° to YURII, then on track 095°. Expect RADAR vectors to final approach course.
LANDING RWYS 8L/R: From MRCHH on track 180° to cross JAGRR at 9000, then on track 180°. Expect RADAR vectors to final approach course.
LANDING RWY 9L: From MRCHH on track 188° to cross BSHOP at 9000, then on track 203° to cross NAVVY at or above 8000, then on track 170° to cross RYENN at or above 7000, then on track 095° to cross AAKAY at or above 6000. Expect ILS Rwy 9L approach.
LANDING RWY 9R: From MRCHH on track 188° to cross BSHOP at 9000, then on track 203° to cross NAVVY at or above 8000, then on track 170° to cross ANDIY at or above 7000, then on track 095° to cross DFINS at or above 6000. Expect ILS Rwy 9R approach.
LANDING RWY 10: From MRCHH on track 188° to cross BSHOP at 9000, then on track 203° to cross NAVVY at or above 8000, then on track 180° to cross DROYD at 8000, then on track 180°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS
LANDING WEST: ASSIGNED RWY 26R OR RWY NOT ASSIGNED: Cross CHPPR at 13000; cross RAIIN at 12000; cross SWEPT at or above 7000; cross KEAVY at 5000; after KEAVY turn right direct ZELOW and proceed on the ILS or RNAV Rwy 26R approach.
LANDING WEST: ASSIGNED RWY 26L: Cross CHPPR at 13000; cross RAIIN at 12000; cross SWEPT at or above 7000; cross KEAVY at 5000; after KEAVY turn right direct JIRRI and proceed on the ILS or RNAV Rwy 26L approach.
LANDING WEST: ASSIGNED RWY 27L: Cross CHPPR at 13000; cross EAGYL at 12000; cross FOGER at or above 7000; cross YURII at 4000; after YURII turn left direct SLVAA and proceed on the ILS or RNAV Rwy 27L approach.
LANDING WEST: ASSIGNED RWY 27R: Cross CHPPR at 13000; cross EAGYL at 12000; cross FOGER at or above 7000; cross YURII at 4000; after YURII turn left direct YOUYU and proceed on the ILS or RNAV Rwy 27R approach.
LANDING WEST: ASSIGNED RWY 28: Cross CHPPR at 13000; cross EAGYL at 12000; cross FOGER at or above 7000; cross YURII at 4000; after YURII turn left direct PRMAN and proceed on the ILS or RNAV Rwy 28 approach.
LANDING EAST: ASSIGNED RWY 8L OR RWY NOT ASSIGNED: Cross CHPPR at 13000; cross JAGRR at 9000; after JAGRR descend to 6000 and proceed direct LARII; proceed on the ILS or RNAV Rwy 8L approach.
LANDING EAST: ASSIGNED RWY 8R: Cross CHPPR at 13000; cross JAGRR at 9000; after JAGRR descend to 6000 and proceed direct GPEAT; proceed on the ILS or RNAV Rwy 8R approach.
LANDING EAST: ASSIGNED RWY 10: Cross CHPPR at 13000; cross BSHOP at 9000; cross NAVVY at or above 8000; cross DROYD at 8000; after DROYD descend to 6000 and proceed direct DEWHY; proceed on the ILS or RNAV Rwy 10 approach.