

COLUMBUS

BOLTON FLD (TZR)(KTZR) 8 SW UTC-5(-4DT) N39°54.07' W83°08.22'

CINCINNATI

904 B TPA—1704(800) NOTAM FILE TZR

H-10G, L-29A

RWY 04-22: H5500X100 (ASPH) S-48, D-75, 2S-95, 2D-150 MIRL

IAP, AD

RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 25'.

RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 25'.

SERVICE: S4 **FUEL** 100LL, JET A1+ **OX 3** **LGT** When ATCT clsd actvt
MALSR Rwy 04; REIL Rwy 22; MIRL Rwy 04-22—CTAF.

AIRPORT REMARKS: Attended 1230-0030Z†. Birds & otr wildlife on & invof
arpt. Bln & banner act on & invof arpt. 100LL avbl H24 self svc via
credit card. High tension plines/towers NE-SE. Calm wind Rwy 04.

AIRPORT MANAGER: 614-851-9900

WEATHER DATA SOURCES: AWOS-3PT 135.925 (614) 878-1722. Freq unavbl
1230-0030Z† ctc gnd ctl 121.8 for wx.

COMMUNICATIONS: CTAF 128.1

Ⓡ **COLUMBUS APP/DEP CON** 134.0

TOWER 128.1 (1230-0030Z†) **GND CON** 121.8

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Columbus Apch at
614-338-8537.

AIRSPACE: CLASS D svc 1230-0030Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

APPLETON (VH) (H) VORTAC 116.7 APE Chan 114 N40°09.06'
W82°35.30' 246° 29.4 NM to fld. 1354/6W.

VOR unusable:

025°-030°

TACAN AZIMUTH unusable:

075°-095°

110°-115°

DME unusable:

075°-080°

BOUTN NDB (MHW/LOM) 230 BU N39°49.16' W83°12.28' 037° 5.8 NM to fld. 922/5W. NDB unmonitored
0200-1400Z†.

NDB unusable:

355°-010° byd 15 NM

ILS 111.7 I-BUZ Rwy 04. LOM BOUTN NDB. Unmonitored when ATCT clsd. Glideslope unmonitored when ATCT
clsd. BOUTN NDB unusable 357°-027° byd 10 NM. Autopilot coupled approach NA below 1,144 feet. Glideslope
reversal at 0.61 NM from threshold.

COMM/NAV/WEATHER REMARKS: Emerg frequency not monitored all times. For fuel and acft svcs ctc FBO on 123.3.

