
SALEM AIRPARK (38D) 3 N UTC-5(-4DT) N40°56.88' W80°51.72'

1162 NOTAM FILE CLE

DETROIT

L-30G

RWY 10L-28R: H3404X50 (ASPH) S-8 LIRL(NSTD) 0.3% up E

IAP

RWY 10L: Trees.**RWY 28R:** Thld dsplcd 266'. Hill.**RWY 10R-28L:** 2550X60 (TURF) 0.4% up E**RWY 10R:** Trees.**RWY 28L:** Pole.**SERVICE:** **FUEL** 100LL **LGT** Actvt nstd LIRL Rwy 10L-28R—CTAF. Rwy 10L-28R nstd LIRL due to layout and colors; Rwy 10L lgtd 238' from rwy end; Rwy 28R lgtd 330' from rwy end with 360° green lgts.**AIRPORT REMARKS:** Attended irreg. Deer, birds, and wildlife on and invof arpt. Dragstrip 3500 ft southeast looks like arpt. All pavement restricted acct max gwt less than 8000 lbs. Rwy 10R-28L: ctc amgr for turf conds prior to use. Rwy 10L-28R marking non-standard due to yellow DTHR. Rwy 10L-28R only 2829 ft avbl for ngt ops. Rwy 10L-28R wdspr cracking. Rwy 10L: marking faded. Rwy 28R: marking faded. Rwy 28R: acct on turn fm downwind to base may be obsc by trees in apch. Fuel: 100LL avbl H24 self svc via credit card.**AIRPORT MANAGER:** 724-316-6026**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓡ CLEVELAND APP/DEP CON 125.5 (1100-0600Z‡).

Ⓡ CLEVELAND CENTER APP/DEP CON 120.6 (0600-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE YNG.**YOUNGSTOWN (L) (L) VORTACW** 109.0 YNG Chan 27 N41°19.86' W80°40.48' 205° 24.5 NM to fld. 1159/5W.

VOR unusable:

015°-179° blo 5,000'

180°-014° byd 25 NM blo 5,000'

SANDUSKY CO RGNL (See FREMONT on page 290)

SEAGATE HELISTOP HELIPORT (See TOLEDO on page 320)

SEBRING
TRI-CITY (3G6) 1 SE UTC-5(-4DT) N40°54.36' W81°00.00'

DETROIT

1188 NOTAM FILE CLE

L-29B

RWY 18-36: H2768X45 (ASPH) LIRL(NSTD)

IAP

RWY 36: Pole.**SERVICE:** **FUEL** 100LL **LGT** Actvt NSTD LIRL Rwy 18-36—CTAF. Rwy 18-36 NSTD LIRL due to layout, colors and non-frangible fixtures.**AIRPORT REMARKS:** Unattended. Deer, birds, & wildlife on & invof arpt. Fuel avbl upon request, call amgr. Rwy 18-36 excessive cracking, vegetation thru cracks & joints, & uneven rough pavement. Rwy 18 nstd basic due to nrs layout & size. Cntrln faded. Rwy 36 nstd basic due to nrs layout & size. Cntrln faded.**AIRPORT MANAGER:** 330-428-1269**COMMUNICATIONS:** CTAF 122.9

Ⓡ CLEVELAND APP/DEP CON 125.5 (1100-0600Z‡)

Ⓡ CLEVELAND CENTER APP/DEP CON 120.6 (0600-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CAK.**AKRON (L) (L) VORW/DME** 114.4 ACO Chan 91 N41°06.47' W81°12.09' 147° 15.2 NM to fld. 1197/4W.

DME unusable:

Byd 10 NM

SENECA CO (See TIFFIN on page 319)