

**JOHNSON**

**STANTON CO MUNI** (JHN)(KJHN) 2 NE UTC-6(-5DT) N37°35.12' W101°43.94'

**WICHITA**  
L-10G, 15B  
IAP

3325 B NOTAM FILE ICT

**RWY 17-35:** H5200X75 (CONC) S-34, D-46 PCN 11 R/C/X/U MIRL

**RWY 17:** PAPI(P4L)—GA 3.0° TCH 40'.

**RWY 35:** PAPI(P4L)—GA 3.0° TCH 40'.

**RWY 08-26:** H1889X60 (ASPH) S-3 PCN 4 R/C/Y/U

**SERVICE:** S4 FUEL 100LL, JET A OX1 LGT ACTVT MIRL 17-35; to incr instst and ACTVT PAPI Rwy 17 and 35—CTAF.

**AIRPORT REMARKS:** Attended 1400-0000Z±. PAEW adjacent all rwsys. Rwy 08-26 surface cracking. Twy adjacent to Rwy 17-35 parallel twy unmarked.

**AIRPORT MANAGER:** 620-492-2414

**WEATHER DATA SOURCES:** AWOS-3PT 124.175 (620) 492-2100.

**COMMUNICATIONS:** CTAF/UNICOM 122.8


Ⓡ **KANSAS CITY CENTER APP/DEP CON** 125.2

**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LBL.

**LIBERAL (H) TACAN** Chan 70 LBL (112.3) N37°02.66' W100°58.27' 301° 48.8 NM to fld. 2881/11E.

**TACAN AZIMUTH** unusable:  
240°-280°



**JOHNSON CO EXEC** (See OLATHE on page 131)