



## Federal Aviation Administration

---

---

# SAFETY ALERT

Date: October 21, 2013

To: Users of the Airport/Facility Directory (A/FD) East Central volume and digital-A/FD (d-A/FD).

From: Aeronautical Navigation Products (AeroNav Products).

Subject: Port Columbus International (CMH) – Incorrect Hot Spot descriptions.

---

---

**The October 17, 2013 edition of the Airport/Facility Directory (A/FD) East Central (EC) volume and d-A/FD contain incorrect Hot Spot descriptions for Port Columbus International airport (CMH), OH.**

Only one Hot Spot exists at Port Columbus International airport. The correct description is as follows:

**HS-1 Area not visible from the twr.**

This description supersedes the Hot Spot descriptions found on page 443 of the A/FD EC and d-A/FD. The Airport Diagram (AD) for Port Columbus International airport (CMH) in the A/FD is correct.

The revised Hot Spot description can be accessed at the following link:  
[http://aeronav.faa.gov/pdfs/ec\\_hotspot\\_17OCT2013.pdf](http://aeronav.faa.gov/pdfs/ec_hotspot_17OCT2013.pdf)

Published by the  
U.S. DEPARTMENT OF TRANSPORTATION  
Federal Aviation Administration