

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 06/16/2017	<b>Task #:</b> 2017050115560201006	<b>Request #:</b> 20170501155602
<b>Procedure:</b> VOR RWY 5 AMDT 11A			<b>Airport ID:</b> KOTH	<b>Airport:</b> SOUTHWEST OREGON RGNL		<b>Reimbursable #:</b> NO
<b>City:</b> NORTH BEND	<b>ST:</b> OR	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 03/26/2020		<b>FICO #:</b>	
<b>Fac ID:</b> OTH		<b>Fac. Type:</b> VOR_DME			<b>Specialist:</b> KELLY DEAN	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	10/02/2019					
<b>QA:</b>			J ZEDER 12/2/2019 <sup>16</sup>			
<b>Liaison:</b>						
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
ABREV AMDT  POC FOR THIS ACTION IS DON LANIER 405-954-8242  PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED						

VOR/DME RWY 4  
SOUTHWEST OREGON RGNL (OTH)

**MISSED APPROACH:** Climb to 900 then climbing right turn to 3000 on heading 303° and on OTH VOR/DME R-253 to WESEB/8 DME and hold, continue climb-in-hold to 3000.

[illegible]

NW-1, 10 OCT 2019 to 07 NOV 2019

NW-1, 10 OCT 2019 to 07 NOV 2019