

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/09/2021	APWS Task ID: 14D3DB708B414894B9299F362398685B	APWS Project ID: 46ACC81E4AEF46CD82D1BD5511AB7193
Procedure: RNAV (GPS) RWY 23 AMDT 0B		Enroute: NO	Specialist: Lafferty, James		Agreement Number:
Airport ID: KLQK			Airport City: PICKENS		State: SC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div> <div> Procedure Comments:</div> <div> P-NOTAM This Cancels FDC 0/9894 Order 8260.3, chapter 2, New Circling Criteria Applied Contact Dave Teffeteller at 202-267-5177 </div> <div> <div>QUALITY 45 CHECKED</div> <div>QUALITY 26 CHECKED</div> </div> </div>					


RNAV (GPS) RWY 23
PICKENS COUNTY (LOK)

MISSED APPROACH:
Climb to 3000 direct
ZAKOB and hold.

UNICOM
122.8 (CTAF) 



1956



PICKENS COUNTY (LOK)

RNAV (GPS) RWY 23

SE-2, 12 JAN 2012 to 09 FEB 2012

