



| | | | | | |
|--|-------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page | Task Action: P-NOTAM | Task Type: IAP | Estimated Chart Date: 01/27/2022 | APWS Task ID: 188232864C534D6F8E196F5E4D2E766E | APWS Project ID: 8092CF2037AB4AABA96C00A04C0E42B1 |
| Procedure: RNAV (GPS) RWY 11 AMDT 0H | | Enroute: NO | Specialist: Hanby, William | | Agreement Number: |
| Airport ID: KEWR | | Airport City: NEWARK | | State: NJ | |
| Facility ID: | Facility Type: | Flight Inspection Remark Type: | | | |
| <p>Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/21, GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION</p> <p>PAPI-4R LIGHTS COMMISSIONED ON 7/15/21, VGSI AND DESCENT ANGLES NOT COINCIDENT.</p> <p>KEWR ACTIVE DATA USED FOR AIRPORT, PENDING DATA 12/02/21 USED FOR RWY 11.</p> <p>THIS P-NOTAM CANCELS FLIGHT INSPECTION NOTAM FDC 1/0724.</p> <p>CONTACT MR. JOHN BORDY, IFP Team 2, Sub-Team B, AJV-A422 AT 405-954-0980.</p> | | | | | |





Digitally signed by

PABLO ORTIZ-JR

Nov 16, 2021