





Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 08/10/2023	APWS Task ID: 1AB97BB17E584A9AAD8AD46E25C295D9	APWS Project ID: 27E5F77C53444E239F8BF41254EECBF1
Procedure: VOR RWY 1 AMDT 10		Enroute: NO	Specialist: Martinez, Rafael		Agreement Number:
Airport ID: PADL			Airport City: DILLINGHAM		State: AK
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<div>Procedure Comments:</div> <div>FULL AMENDMENT.</div> <div>PENDING DATA USED FOR PADL AIRPORT AND RUNWAY (08-10-23).</div> <div>CONTACT: JOHNNIE BAKER: 405-202-5148/DAVID TEFFETELLER 202-267-5177.</div> <div><div>J ZEDER 08/25/2023</div><div>QUALITY 16 CHECKED</div><div>QUALITY 38 CHECKED</div></div>					

DILLINGHAM (DLG)(PADL)
VOR RWY 1









PADL
DILLINGHAM
DILLINGHAM, AK
RWY 1 VOR
AMDT 10

FINAL, MISSED, CIRCLING
100K

Circling CAT D
AAO (390)

Circling CAT A/B
TREE (196)
02-030651

Misled Level Surface
TOWER (417)
02-000122

RW19

PADL

RW01

DLG

Final
VOR:DLG:VOR/DME to RW01
TREE (175)

Circling CAT C
TOWER (261)
02-000617

