

| | | | | | |
|--|---------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page | Task Action: Amendment | Task Type: FIX | Estimated Chart Date: 08/07/2025 | APWS Task ID: 1CCB266342D649FD9F8E7C6308D08923 | APWS Project ID: C62C0E548AA34F24BC7D881DDC877336 |
| Procedure: FIX IMPOR 2 WA US | | Enroute: NO | Specialist: Bruce, Richard | | Agreement Number: |
| Airport ID: | | | Airport City: | | State: |
| Facility ID: | Facility Type: | Flight Inspection Remark Type: | | | |
| <div>Procedure Comments:</div> <div>VICTORIA (YYJ) VOR/DME CONVERSION TO STAND-ALONE DME.</div> <div>MULTIPLE FIXES (2): FIX BUICK REV 4 CA (CANADA). FIX IMPOR REV 2 WA US.</div> <div>CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711.</div> <div>06/11/25: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 04/15/25. 8260-2 FOR FIX BUICK: 1. FIX MAKE-UP FACILITIES: DELETED VANCOUVER (YVR) VOR/DME. 2. FIX USE: NDB RWY 34 AT KFHR, DELETED USE OF FAC 1.</div> <div>QUALITY 35 CHECKED</div> | | | | | |