

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> FLIGHT CHECK	<b>Task Type:</b> IAP	<b>Date Open:</b> 11/13/2014	<b>Task #:</b> 2014111330762106002	<b>Request #:</b> 20141113307621
<b>Procedure:</b> RNAV (GPS) RWY 35 AMDT 0B			<b>Airport ID:</b> KT45	<b>Airport:</b> PANHANDLE-CARSON COUNTY		<b>Reimbursable #:</b> NO
<b>City:</b> PANHANDLE	<b>ST:</b> TX	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 07/21/2016			<b>FICO #:</b>
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>			<b>Specialist:</b> DAN CAIRNS	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	10/21/2015					
<b>QA:</b>				4 2/9CTabaka		
<b>Liaison:</b>						
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
REQUEST TABLE TOP.						
CONTACT: JACOB POWERS/PETE GETZ, AJV-5423 LEADS, 405.954.8702/4919.						

APP CRS	Rwy Idg	4404
352°	TDZE	3454
	Apt Elev	3454

RNAV (GPS) RWY 35  
PANHANDLE-CARSON COUNTY (T45)

<p><b>NA</b></p> <p>DME/DME RNP-0.3 NA. Use Amarillo Intl altimeter setting; when not received, use Hutchinson County altimeter setting and increase all MDA 40 feet; increase LNAV Cat C visibility to 2 miles.</p>	<p>MISSED APPROACH: Climb to 5500 direct JASMI and hold.</p>
--	--

AMARILLO APP CON ★ 119.5 307.0	UNICOM 122.7 (CTAF)	123.5 <b>0</b>
-----------------------------------	------------------------	----------------

