


| | | | | | | |
|---|---------------|-----------------------------|---|---|---------------------------------------|-------------------------------------|
| Flight Procedure Tracking Form | | Action: AMENDMENT | Task Type: IAP | Date Open: 01/28/2017 | Task #: 2017012825909702005 | Request #: 20170128259097 |
| Procedure: RNAV (GPS) Y RWY 35L AMDT 4B | | | Airport ID: KOKC | Airport: WILL ROGERS WORLD | | Reimbursable #: NO |
| City: OKLAHOMA CITY | ST: OK | GPS #: | Estimated Chart Date: 12/07/2017 | | FICO #: 1192406 | |
| Fac ID: N/A | | Fac. Type: | | | Specialist: LIAM DONAHUE | |
| Procedure Review | | | | | | |
| | Rec'd | Rel'd | Full Name | Comments <i>Digitally signed by</i> | | |
| Lead: | 03/01/2017 | 09/19/2017 | DONALD LANIER |  DONALD H LANIER Sep 22, 2017 | | |
| QA: | 09/19/2017 | 08/10/2017 | DAVID DANNER | | | |
| Liaison: | 08/10/2017 | 08/10/2017 | MARY MCDONALD | | | |
| Procedure Comments: | | | ENROUTE-NON | Remark Type: INFORMATION | | |
| <p>REQUEST FC TABLETOP.</p> <p>09/22/17: THIS IS A CORRECTED COPY OF THE 8260-2 FOR CUBTU APPROVED ON 08/31/17.</p> <p>1. CHANGED HOLDING PATTERN 2 RAD/CRS/BRG FROM 174.96 TO 175.96.</p> <p>2. CHANGED ILS OR LOC/DME RWY 35L AT KOKC TO ILS OR LOC RWY 35L IN FIX USE.</p> <p>CONTACT: JACOB POWERS/BEV BORDY 405.954.8702/405.954.8293.</p> | | | | | | |

