

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 07/18/2018	<b>Task #:</b> 2017042728787801007	<b>Request #:</b> 20170427287878
<b>Procedure:</b> VOR RWY 9 AMDT 4E			<b>Airport ID:</b> KLAL	<b>Airport:</b> LAKELAND LINDER INTL		<b>Reimbursable #:</b> NO
<b>City:</b> LAKELAND	<b>ST:</b> FL	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 02/28/2019		<b>FICO #:</b>	
<b>Fac ID:</b> LAL		<b>Fac. Type:</b> VORTAC			<b>Specialist:</b> LIAM DONAHUE	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	08/23/2018	11/14/2018	ANDI LAU			
<b>QA:</b>	10/11/2018			12/17CTabaka		
<b>Liaison:</b>						
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
<p>PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.</p> <p>CONTACT: DON LANIER, AJV, 5431 MANAGER, 405.954-8242</p> <p>12/14/18: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 11/14/18.</p> <p>1. MALSR CHANGED TO ALS IN BACKUP ALTIMETER INOPERATIVE LIGHTING NOTE.</p>						