

Flight Procedure Tracking Form		Action: FLIGHT CHECK	Task Type: IAP	Date Open: 06/14/2017	Task #: 2017061431033302001	Request #: 20170614310333
Procedure: APPROACH RNAV (GPS) RWY 5 ORIG-B			Airport ID: K20A	Airport: ROBBINS FIELD		Reimbursable #: NO
City: ONEONTA	ST: AL	GPS #:	Estimated Chart Date: 09/14/2017			FICO #:
Fac ID: N/A		Fac. Type:			Specialist:	
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:				QUALITY		
QA:				13 07/07/17 L.Zuest		
Liaison:				CHECKED		
Procedure Comments:			ENROUTE-NON			
			Remark Type:		INFORMATION	
FLIGHT INSPECTION REVIEW NOT REQUIRED - PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017. P-NOTAM						

APP CRS	Rwy Idg	4203
058°	TDZE	1121
	Apt Elev	1125

RNAV (GPS) RWY 5

ROBBINS FIELD (20A)

▼

NA

DME/DME RNP-0.3 NA. Procedure NA at night. Use Albertville Rgnl altimeter setting, when not received, use Northeast Alabama Rgnl altimeter setting and increase all MDA 60 feet and increase Cat C visibility 1/8 mile. Helicopter visibility reduction below 1 SM NA.

MISSED APPROACH: Climb to 4000 direct CEPET and hold.

ALBARTVILLE RGNL AWOS-3 119.575	ATLANTA CENTER 127.3 251.05	UNICOM 122.8 (CTAF) 0
------------------------------------	--------------------------------	--------------------------

