


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 08/10/2017	<b>Task #:</b> 2017081032094201007	<b>Request #:</b> 20170810320942
<b>Procedure:</b> RNAV (GPS) RWY 23 AMDT 2B			<b>Airport ID:</b> KCAE	<b>Airport:</b> COLUMBIA METROPOLITAN		<b>Reimbursable #:</b> NO
<b>City:</b> COLUMBIA	<b>ST:</b> SC	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 10/12/2017		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>			<b>Specialist:</b> LIAM DONAHUE	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	08/10/2017			 <i>Digitally signed by</i>		
<b>QA:</b>				<b>20 BRIAN J BICKETT</b>		
<b>Liaison:</b>				Aug 31, 2017		
<b>Procedure Comments:</b> ENROUTE-NON <b>Remark Type:</b> INFORMATION  FLIGHT INSPECTION REVIEW NOT REQUIRED-PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017.  CONTACT: DON LANIER, AJV, 5431 MANAGER, 405.954-8242						