

[Print](#)

Project Name: TVF - VOR RWY 31

Project Reason: TEAM 1 (LEIDOS) - DURING A PERIODIC REVIEW A NEW CONTROLLING OBSTACLE WAS IDENTIFIED WHICH AFFECTS STRAIGHT IN MINIMA AND CIRCLING CATS A/B/C. INCREASE STRAIGHT IN MDA TO 1600FT ALL CATS. INCREASE CIRCLING MDA CAT A, CAT B AND CAT C TO 1600FT. OBSTACLE 27-026886, 475934.00N/0955840.00W, 1470FT MSL, (4D) ACCURACY, 330FT AGL. UPDATED MISSED APPROACH INSTRUCTIONS TO CHANGE "VIA" TO "ON". "VIA" NO LONGER USED. PER VISI CHECK, CAT C VISIBILITY INCREASE TO 1. UPDATED HATS AND HAAS DUE TO NEW AIRPORT INFORMATION. AIRPORT ELEV 1119 AND TDZE 1114.

Last Updated By: Tommy Byrns

Last Updated At: 2017-09-15 19:01:01.243252

Status: Verified **7/5050**

IFDC X/XXXX TVF IAP THIEF RIVER FALLS RGNL, Thief River Falls, MN. VOR RWY 31, AMDT 8C... DELETE TDZE 1113, CHART TDZE 1114. CHART APT ELEV 1119. S-31 MDA 1660/HAT 546 ALL CATS, VISIBILITY CAT C/D 1-1/8. CIRCLING CATS A/B/C MDA 1660/HAA 541, VISIBILITY CAT C 1-5/8. CIRCLING CAT D HAA 561. CHANGE MISSED APPROACH INSTRUCTIONS TO READ: CLIMB TO 2700 ON TVF R-297 THEN LEFT TURN DIRECT TVF VOR/DME AND HOLD. THIS IS VOR RWY 31, AMDT 8D. 1709151900-PERM

*Digitally signed by*

**VICTOR B NASO**

Sep 22, 2017

