

[Print](#)

Project Name: BFL VGSI RWY 30R COMMISSIONING

Project Reason: RWY 30R VGSI RELOCATED 08/15/17 AND NOT FLIGHT INSPECTED/COMMISSIONED. VGSI ANGLE: 3.00/TCH 50.7'. DELETED VGSI NON-COINCIDENT PROFILE FROM ILS OR LOC RWY 30R AND RNAV (GPS) RWY 30 SIAPS. CHANGED APPROACH LIGHTING SYSTEM ACRONYM FROM: MASLR, TO ALS IN THE INOPERATIVE NOTES FOR THESE SIAPS. FOR THE RNAV (GPS) RWY 30R, DELETED CHART NOTE: DME/DME RNP-0.3 NA. ADDED CHART NOTE: EQUIPMENT REQUIREMENTS NOTE: RNP APCH.

Last Updated By: ROBERT COOK

Last Updated At: 2018-02-23 12:09:38.04566

Status: Verified

8/2901
!FDC X/XXXX BFL IAP MEADOWS FIELD, Bakersfield, CA. RNAV (GPS) RWY 30R, AMDT 2A... CHART NOTE: FOR INOPERATIVE ALS WHEN USING PORTERVILLE ALTIMETER SETTING, INCREASE LPV ALL CATS VISIBILITY TO RVR 5000 AND LNAV CAT C AND D VISIBILITY TO 1 3/8. DELETE NOTE: FOR INOPERATIVE MALSRL WHEN USING PORTERVILLE ALTIMETER SETTING, INCREASE LPV ALL CATS VISIBILITY TO RVR 5000 AND LNAV CAT C AND D VISIBILITY TO 1 3/8. DELETE PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 67). DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. THIS IS RNAV (GPS) RWY 30R, AMDT 2B. 1802231209-PERM

Digitally signed by

BEV L BORDY

May 24, 2018

