

[Print](#)

Project Name: SEA - RVR 1800 note removal

Project Reason: ILS OR LOC RWY 34C: 1. RVR 1800 note removed - not authorized by note due to HAT > 200. 2. "DME or RADAR Required" in both Notes box and Planview converted to Equipment Requirements Note due to current policy. 3. RNAV-1 note added due to current policy. 4. Planview note next to SONDR "GPS Req'd" replaced by Equipment Requirements Note due to current policy. 5. Apt Elev updated from 433 to 432, circling HAAs adjusted due to new survey data. RNAV (GPS) Y RWY 34C: 1. RVR 1800 note removed - not authorized by note due to HAT > 200. 2. DME/DME RNP-0.3 NA note replaced with PBN Equipment Note. 3. Apt Elev updated from 433 to 432, circling HAAs adjusted due to new survey data. 4. Planview note wording changed from "via" to "on" due to current policy. RNAV (GPS) Y RWY 16L: 1. RVR 1800 note removed - not authorized by note due to HAT > 200. 2. DME/DME RNP-0.3 NA note replaced with PBN Equipment Note. 3. Apt Elev and TDZE updated from 433 to 432, HAA/HATs adjusted due to new survey data.

Last Updated By: Russell Roslewski

Last Updated At: 2018-04-24 14:00:03.505335

Status: Verified

8/6627

!FDC X/XXXX SEA IAP SEATTLE-TACOMA INTL, Seattle, WA. RNAV (GPS) Y RWY 34C, AMDT 2C... DELETE NOTE: #RVR 1800 AUTHORIZED WITH USE OF FD OR AP OR HUD TO DA. CHANGE LPV DA# TO LPV DA. DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. CHART APT ELEV 432, DELETE APT ELEV 433. CIRCLING HAA 568 ALL CATS. DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT CIDUG VIA V495 SOUTHBOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT CIDUG ON V495 SOUTHBOUND. THIS IS RNAV (GPS) Y RWY 34C, AMDT 2D. 1804241400-PERM

Digitally signed by

DEZ SILAGYI

Apr 27, 2018

