


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 02/23/2018	<b>Task #:</b> 201802172761813V002	<b>Request #:</b> 20180217276181
<b>Procedure:</b> APPROACH RNAV (GPS) RWY 20 AMDT 1A				<b>Airport ID:</b> KI74	<b>Airport:</b> GRIMES FIELD	<b>Reimbursable #:</b> NO
<b>City:</b> URBANA	<b>ST:</b> OH	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 08/16/2018		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>			<b>Specialist:</b> LIAM DONAHUE	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>		<b>Comments</b>	
<b>Lead:</b>	02/23/2018					
<b>QA:</b>						
<b>Liaison:</b>						
<b>Procedure Comments:</b>			<b>ENROUTE-NON</b> <b>Remark Type:</b> INFORMATION			
P-NOTAM 8/7456 FLIGHT INSPECTION REVIEW NOT REQUIRED-PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017.  CONTACT: DON LANIER, AJV, 5431 MANAGER, 405.954-8242						