

[Print](#)

Project Name: HWD RWY 28L IAP NEW MISSED HOLDING ALTITUDE.

Project Reason: FPT IDENTIFIED NEW HOLDING CONTROLLING OBSTACLE 1090 MSL BLDG (06-038966) AC 5E VGSI NOTES AND HELICOPTER VISIBILITY NOTES UPDATED PER NEW CRITERIA.

Last Updated By: liam donahue

Digitally signed by

Last Updated At: 2019-01-30 19:48:36.5528

DONALD H LANIER

Jan 31, 2019

Status: Verified FDC 9/9129

!FDC X/XXXX HWD IAP HAYWARD EXECUTIVE, Hayward, CA. VOR/DME-A, AMDT 3A... DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA. DELETE NOTE: WHEN VGSI INOP CIRCLING TO RWY 10L-28R NA AT NIGHT. CHANGE MISSED APPROACH TO READ: CLIMB TO 2100 DIRECT OAK VOR/DME AND HOLD. THIS IS VOR/DME-A, AMDT 3B. 1901301948-PERM

