



Project Name: KJFK - ILS OR LOC RWY 4L CORRECT LOC CAT B VISIBILITY.

Project Reason: S-LOC 04L CAT B VIS INCREASED FROM RVR 5000 TO RVR 5500. CORRECTED ALTERNATE MINIMUMS DUE TO ERROR.

Last Updated By: RAFAEL A MARTINEZ

Last Updated At: 2018-08-09 14:30:10.024915

Status: Verified **8/8694**

!FDC ~~XXXXX~~ JFK IAP JOHN F KENNEDY INTL, New York, NY. ILS OR LOC RWY 4L, AMDT 11B ... S-LOC 4L VIS CAT B RVR 5500. ALTERNATE MINIMUMS: ILS: STANDARD; LOC: STANDARD. THIS IS ILS OR LOC RWY 4L, AMDT 11C. 1808091430-PERM



Digitally signed by
DAVID TEFFETELLER
Aug 28, 2018