

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 10/04/2018	<b>Task #:</b> 2018100432704901001	<b>Request #:</b> 20181004327049
<b>Procedure:</b> APPROACH RNAV (GPS) RWY 17 AMDT 1B			<b>Airport ID:</b> KT23	<b>Airport:</b> ALBANY MUNI		<b>Reimbursable #:</b> NO
<b>City:</b> ALBANY	<b>ST:</b> TX	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 12/06/2018		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>		<b>Specialist:</b> RUSSELL CRONK		
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	10/04/2018					
<b>QA:</b>			J ZEDER 10/11/2018	QUALITY 16		
<b>Liaison:</b>				CHECKED		
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
<p>P-NOTAM TO CORRECT T-NOTAM. 8/3873</p> <p>FLIGHT INSPECTION REVIEW NOT REQUIRED - PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-333) MEMO, DEC 22, 2017.</p> <p>CONTACT: DON SMITH AJV-5413 SUB TEAM MANAGER, 405-954-8222; OR BEVERLY BORDY AJV-5411 SUB TEAM MANAGER, 405-954-8293.</p>						