

[Print](#)

Project Name: CHO - ILS OR LOC RWY 3 Restoral of JITIV FIX MINIMUMS S-LOC

Project Reason: PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED. Restore JITIV FIX MINIMUMS S-LOC 3 to previous values. JITIV FIX MINIMUMS S-LOC 3 were raised via P-NOTAM, but EFPT advised the MA penetration, 783 MSL TREE (51-058717) 380801.79N-0782731.60W, AC 1A, had been removed and was not a factor.

Last Updated By: JOHN THORNTON

Last Updated At: 2018-11-07 22:09:32.77259

Status: Verified
8/2275

!FDC X/XXXX CHO IAP CHARLOTTESVILLE-ALBEMARLE, Charlottesville, VA. ILS OR LOC RWY 3, AMDT 1A... JITIV FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED): S-LOC 3 MDA 980/HAT 340 ALL CATS. THIS IS ILS OR LOC RWY 3, AMDT 1B. 1811072209-PERM

Digitally signed by

MARK D ADAMS

Nov 08, 2018

