


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 12/06/2018	<b>Task #:</b> 2018120632042001001	<b>Request #:</b> 20181206320420
<b>Procedure:</b> NDB RWY 25 AMDT 15B			<b>Airport ID:</b> KAKR	<b>Airport:</b> AKRON FULTON INTL		<b>Reimbursable #:</b> NO
<b>City:</b> AKRON	<b>ST:</b> OH	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 05/23/2019		<b>FICO #:</b>	
<b>Fac ID:</b> AKR		<b>Fac. Type:</b> LOC			<b>Specialist:</b> STEVEN DOUGHERTY	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	12/13/2018	02/07/2019	DAVID FRESELLA			
<b>QA:</b>	02/07/2019					
<b>Liaison:</b>						
<b>Procedure Comments:</b> ENROUTE-NON <b>Remark Type:</b> INFORMATION  PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED  PENDING DATA USED.  CONTACT ROBERT HAMILTON (405) 954-4608.						