


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 06/03/2019	<b>Task #:</b> 2019060327866701001	<b>Request #:</b> 20190603278667
<b>Procedure:</b> ILS OR LOC RWY 27 AMDT 11B			<b>Airport ID:</b> KIAH	<b>Airport:</b> GEORGE BUSH INTERCONTINENTAL/HOUSTON		<b>Reimbursable #:</b> NO
<b>City:</b> HOUSTON	<b>ST:</b> TX	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 12/05/2019		<b>FICO #:</b>	
<b>Fac ID:</b> GHI		<b>Fac. Type:</b> ILS			<b>Specialist:</b> MICAH HILLEY	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	06/03/2019					
<b>QA:</b>						
<b>Liaison:</b>						
<b>Procedure Comments:</b> ENROUTE-NON <b>Remark Type:</b> INFORMATION  INCORPORATED !FDC 9/7287  PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCT 03, 2018, SUBJECT: FLIGHT INSPECTION NOT REQUIRED  CONTACT DONALD LANIER 405-954-8242						