


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> FIX	<b>Date Open:</b> 08/28/2019	<b>Task #:</b> 2019082832410701001	<b>Request #:</b> 20190828324107
<b>Procedure:</b> FIX WITCH 12 MA US			<b>Airport ID:</b> MA	<b>Airport:</b>		<b>Reimbursable #:</b> NO
<b>City:</b>	<b>ST:</b> MA	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 01/30/2020		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>		<b>Specialist:</b> TARA MARTINELLI		
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	08/29/2019			<div style="text-align: center;">  </div>		
<b>QA:</b>						
<b>Liaison:</b>						
<b>Procedure Comments:</b> ENROUTE-NON <b>Remark Type:</b> INFORMATION  UPDATED FIX WITCH FOR CHARTING: REMOVED FAC 1 FROM KLWM IAP ILS OR LOC RWY 05.  FLIGHT INSPECTION REVIEW NOT REQUIRED - PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017.  CONTACT: DON LANIER (405) 954-8245.						