

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/09/2021	APWS Task ID: FF785DA8999F497D9B02832A3D7E033D	APWS Project ID: 4FBE8428D16F48AEAE03C333C80FEBB6
Procedure: RNAV (GPS) RWY 17 AMDT 0A		Enroute: NO	Specialist: Lafferty, James		Agreement Number:
Airport ID: 8V7			Airport City: SPRINGFIELD		State: CO
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments:</p> <p>P-NOTAM</p> <p>This Cancels FDC 0/7870</p> <p>Order 8260.3, chapter 2, New Circling Criteria Applied</p> <p>Contact Dave Teffeteller at 202-267-5177</p>					




APP CRS 171°	Rwy Idg 5000
	TDZE 4390
	Apt Elev 4390

RNAV (GPS) RWY 17

SPRINGFIELD MUNI (8V7)

<p>NA</p> <p>Use Lamar altimeter setting, if not received use La Junta altimeter setting and increase all MDAs 20 feet. DME/DME RNP-0.3 NA.</p>	<p>MISSED APPROACH: Climbing right turn to 10000 direct IYATA and hold, continue climb-in-hold to 10000.</p>
--	---

LAMAR MUNI ASOS 135.625	DENVER CENTER 133.4 377.175	CTAF 122.9
-----------------------------------	---------------------------------------	----------------------



SW-1, 12 SEP 2019 to 10 OCT 2019

SW-1, 12 SEP 2019 to 10 OCT 2019

