

|  |                           |                                |                                     |   |  |
|--|---------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page   | Task Action:<br>Amendment | Task Type:<br>FIX              | Estimated Chart Date:<br>11/03/2022 | APWS Task ID:<br>27F86339023B48A39D466F6741845B50 | APWS Project ID:<br>6C15415DDABF4C258C364DA1F8F52C29 |
| Procedure:<br>FIX JANVO 2 AK US  |                           | Enroute:<br>NO                 | Specialist:<br>Keefer, John         |   | Agreement Number:                                    |
| Airport ID:  |                           |                                | Airport City:                       |   | State:   |
| Facility ID:   | Facility Type:            | Flight Inspection Remark Type: |                                     |   |  |
| <p><b>Procedure Comments:</b><br/> Remove R39 from fix use.<br/> PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.<br/> Contact Casmir Tabaka 405-954-7931.</p> |                           |                                |                                     |   |  |