

[Print](#)

Project Name: M17 RWY 18 VGSI NOTE NEEDED

Project Reason: VGSI 3.75/40 NOT COINCIDENT WITH PROCEDURE DESIGN 3.04/38. REVISED AIRNAV DATA VGSI ANGLE 3.75/TCH 40. ANGLE/TCH NOT WITHIN COINCIDENT CRITERIA

Last Updated By: CHRISTOPHER MENDENHALL

Digitally signed by

Last Updated At: 2024-05-20 13:13:50.361191

DAVID DANNER

Jul 15, 2024

Status: Verified

!FDC 4/0686 M17 IAP BOLIVAR MUNI, BOLIVAR, MO. RNAV (GPS) RWY 18, ORIG-A... LNAV VISIBILITY CAT C 1 3/8. PBN REQUIREMENTS NOTE: RNP APCH - GPS. DELETE NOTE: DME/DME RNP-0.3 NA. CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT (VGSI ANGLE 3.75/TCH 40). CHART NOTE: RWY 18 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. 20:1 IS NOT CLEAR. THIS IS RNAV (GPS) RWY 18, ORIG-B. 2405201313-PERM

