

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 12/30/2021	APWS Task ID: 3FE9DE62138248FDB878EFD358C26599	APWS Project ID: 478EFA20910F4FBCA889C8697F39294D
Procedure: VOR/DME-A AMDT 1C		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KAIK			Airport City: AIKEN		State: SC
Facility ID: IRQ	Facility Type: VORTAC	Flight Inspection Remark Type:			
<p>Procedure Comments: PNOTAM CIRCLING RADII INCREASE</p> <p>CONTACT: JASON KRETSCHMER AJV-A421 LEAD: 405.954.4019</p> <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <p><i>Digitally signed by</i> JASON KRETSCHMER Oct 27, 2021</p> </div> <div style="text-align: center;"> <p><i>Digitally signed by</i> MARY MCDONALD Oct 18, 2021</p> </div> </div>					

QUALITY
47
CHECKED

QUALITY
12
CHECKED

VORTAC IRQ
113.9
Chan 86

APP CRS
102°

Rwy Idg
TDZE
Apt Elev
N/A
N/A
528

OLD

VOR/DME-A
AIKEN RGNL (AIK)

▼

▲ NA

When local altimeter setting not received, use Augusta Rgnl at Bush Fld altimeter setting and increase all MDA 120 feet and increase Cat D visibility ¼ mile.

MISSED APPROACH: Climb to 1600 then climbing left turn to 2400 on IRQ VORTAC R-102 to BEARS/IRQ 19 DME and hold.

AWOS-3 118.025	AUGUSTA APP CON ★ 119.15 284.625	CLNC DEL 126.075	UNICOM 122.8 (CTAF) 1
-------------------	-------------------------------------	---------------------	--------------------------



