

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 03/21/2024	APWS Task ID: 4E4DC77405234BEA8DE009872B4F812F	APWS Project ID: 7A2047264E5E4E8FB53775459474FB9B
Procedure: FIX KKONG 1 NJ US		Enroute: NO	Specialist: Leete, Joshua		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: STAND ALONE FIX PROJECT TO CORRECT FIX KKONG - PAT 1 RADIAL/COURSE/BEARING CHANGED FROM 227.81 TO 047.81. CONTACT: RAKE MCGRAW, TEAM 2 SUBTEAM-B MANAGER: (405) 954-8711.</div> <div>QUALITY 6 SN 2/7/24 CHECKED</div>					