

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 09/05/2024	APWS Task ID: 503CEC5D03F145A5992CA023AA457C9C	APWS Project ID: AF2A07B41A1948408257C9C300F53643
Procedure: VOR RWY 24 AMDT 1		Enroute: NO	Specialist: Marsh, Andre		Agreement Number:
Airport ID: KHKY			Airport City: HICKORY		State: NC
Facility ID: BZM	Facility Type: VOR_DME	Flight Inspection Remark Type: Hold FC Slot			
<div>Procedure Comments:</div> <div>CANCEL FDC NOTAM 2/2775</div> <div>JASON KRETSCHMER: 405-954-4019</div> <div>06/04/24: THIS IS AN UPDATED COPY OF THE FORM DEVELOPED ON 05/01/23.</div> <div>1. CHANGED TERMINAL ROUTES "LANYI/3.00 DME TO SMALZ/6.00 DME" TO "LANYI/3.00 DME TO SMUGG/6.00 DME".</div> <div>2. CHANGED PROFILE: LINE 3, FAF: FROM "SMALZ/6.00 DME" TO "SMUGG/6.00 DME".</div> <div>3. CHANGED PROFILE: LINE 4, MIN ALT: FROM "BZM VOR/DME 4000, LANYI/3.00 DME 3400, SMALZ/6.00 DME 2600" TO "BZM VOR/DME 4000, LANYI/3.00 DME 3400, SMUGG/6.00 DME 2600".</div> <div>4. CHANGED NOTE IN ADDITIONAL FLIGHT DATA: FROM "SMALZ TO RW24: 3.15/54" TO "SMUGG TO RW24: 3.15/54".</div> <div>SMUGG -2:</div> <div>1. FIX NAME CHANGED FROM SMALZ TO SMUGG.</div>					


QUALITY
33
CHECKED

QUALITY
29
CHECKED

FIG

VOR RWY 24
HICKORY RGNL (HKY)

MISSED APPROACH: Climbing right turn to 4000 on heading 340° and BZM R-274 to BZM VOR/DME and hold.

EQUIPMENT REQUIREMENTS NOTE:
DME REQUIRED

HICKORY RGNL (HKY)
VOR RWY 24

35°44'N-81°23'W

22195

VOR/DME RWY 24
HICKORY RGNL (HKY)

MISSED APPROACH: Climbing right turn to 4000 via heading 340° and BZM R-274 to BZM VOR/DME and hold.

[illegible]

SE-2, 18 MAY 2023 to 15 JUN 2023

SE-2. 18 MAY 2023 to 15 JUN 2023

ELEV 1190

D TDZE 1190

61

4400 X 150

0.6 NM UP

1251

6401 X 150

1223

229° 5 NM from FAF

A

P

A5

V

HIRL Rwy 6-24 **L**

MIRL Rwy 1-19 **L**

REIL Rwy 1 **L**

REIL Rwy 6 and 19

HICKORY RGNL (HKY)
VOR/DME RWY 24

