

Flight Procedures Cover Page	Task Action: Amendment	Task Type: IAP	Estimated Chart Date: 09/10/2020	APWS Task ID: 53BA7BB0946649ABAD72E3B1101FB1F6	APWS Request ID: DD0546388FA04BE2A8DAC71A3A29A60D
Procedure: ILS OR LOC RWY 23 AMDT 31A		Enroute: NO	Specialist: Lafferty, James		Agreement Number:
Airport ID: KCRW	Airport Name: YEAGER		Airport City: CHARLESTON		State: WV
Facility ID:	Facility Type:	Flight Inspection Remark Type:			


Procedure Comments:

ACTIVE DATA USED FOR PROCEDURE AMENDMENT.

CANCELS NOTAMs 0/7899 and 9/7285.



PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT:
FLIGHT INSPECTION REVIEW NOT REQUIRED.

CONTACT DAVE TEFFETELLER AT 202-267-5177.



LOC/DME I-CRW 110.3 Chan 40	APP CRS 235°	Rwy Idg 5800 TDZE 931 Apt Elev 947
---	------------------------	---

ILS or LOC RWY 23
YEAGER (CRW)

DME or RADAR required.			MISSED APPROACH: Climb to 1800 then climbing right turn to 3000 direct HVQ VOR/DME and hold.	
				
ATIS 127.6	CHARLESTON APP CON 124.1 269.125	CHARLESTON TOWER 125.7 257.8	GND CON 121.8 348.6	CLNC DEL 118.55

