

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 11/28/2024	APWS Task ID: 55653B5FCCD2494FA51A8BC0C7904139	APWS Project ID: 05B9D042080641F9AC90DA18B46A0DFD
Procedure: FIX ROBEY 4 TX US		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>EDITED HOLDING PATTERN AT FIX</div> <div>Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation</div> <div>CONTACT MR. ROBERT HAMILTON, MANAGER AJV-A433 AT 405-954-4608. FEDERAL AVIATION ADMINISTRATION</div>					

QUALITY  
13  
CHECKED