

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 05/19/2022	APWS Task ID: 5763E0A56B8D40C888E1C095AA338154	APWS Project ID: CEA512D711A74063996D1AA9C6088AD3
Procedure: RNAV (GPS) RWY 36 AMDT 0B		Enroute: NO	Specialist: Brooks, Charles		Agreement Number:
Airport ID: KLHB			Airport City: HEARNE		State: TX
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: P-NOTAM</div> <div>CIRCLING RADII INCREASE.</div> <div>CONTACT JASON KRETSCHMER, AJV-A421, 405-954-4019</div> <div><div>Digitally signed by <b>JASON KRETSCHMER</b> Mar 12, 2022</div><div>QUALITY 47 CHECKED</div><div>QUALITY 38 CHECKED</div></div>					

20198

RNAV (GPS) RWY 36  
HEARNE MUNI (LHB)

**MISSED APPROACH:** Climb to 2600 direct JUPAX and hold.

123.3 L

MSA RW36 25 NM

2300

1270  $\Delta$

(IAF)  
CAPEG

2100  
-088°  
(10)

2100  
268°  
(10)

(IAF)  
TERHI

ELEV	285		TDZE	284
------	-----	--	------	-----

## RADAR REQUIRED

MIRL Rwy 18-36 **L**

**JUPAX**

\*LNAV only.

RW36

NOTE: 1.7 NM to RW36

DOBEY 1800

HISEM 2100

358°

1800

GP 3.00°  
TCH 40'

CATEGORY	A	B	C	D
LPV DA	484- $\frac{3}{4}$	200 (200- $\frac{3}{4}$ )		NA
LNAV/VNAV DA	534- $\frac{7}{8}$	250 (300- $\frac{7}{8}$ )		NA
LNAV MDA	580-1	296 (300-1)	580- $\frac{7}{8}$ 296 (300- $\frac{7}{8}$ )	NA
CIRCLING	800-1 515 (600-1)	880-1 595 (600-1)	920-1 $\frac{3}{4}$ 635 (700-1 $\frac{3}{4}$ )	NA

HEARNE MUNI (LHB)  
RNAV (GPS) RWY 36



KLHB  
HEARNE MUNI  
RNAV GPS RWY 36  
ORIG B  
1:100,000  
CIRCLING  
THIS MAP CREATED  
FOR CIRCLING ICON  
INITIATIVE

