

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 07/16/2020	APWS Task ID: A9DAD2AC9FAA44FE85A5C32D0EAF3158	APWS Project ID: D870CED545F4490DA2A92F2D9F65F9E7
Procedure: FIX RANCK 5 CA US		Enroute: YES	Specialist: Lindholm, Scott		Agreement Number:
Airport ID:	Airport Name:		Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: RANCK FIX STANDALONE CREATED TO BRING ONTO T333. CONTACT: DONALD LANIER 405-954-8242</div> <div>J ZEDER 05/18/2020 16</div> <div>QUALITY CHECKED</div>					