

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 07/14/2022	APWS Task ID: 5A1AC4A976014A45832046AF517C58DA	APWS Project ID: 4A13469E818A40EE8D37FE38467B0275
Procedure: FIX GASTO 10 AK US		Enroute: YES	Specialist: Sickels, Dale		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: MULTIPLE AK FIX PROJECT: GASTO REV 10 - ENROUTE KAYTI REV 2 - NON-ENROUTE  CONTACT JASON KRETSCHMER, AJV-A421, 405-954-4019  04/04/2022: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 03/12/2022: 8260-2: FIX GASTO. ADDED PAT 2, CONTROLLING OBSTACLE FOR PAT 2, PAT 2 TRAFFIC DECONFLICTION TO REASON FOR NON-STANDARD HOLDING, PAT 2 GASTO ONE RNAV DP TO PROCEDURES REQUIRING CLIMB IN HOLD, AND PAT 2 TO FIX USE FOR GASTO ONE RNAV SPECIAL DP.</div> <div><div>QUALITY 14 CHECKED</div><div>QUALITY 47 CHECKED</div><div>Digitally signed by <b>JASON KRETSCHMER</b> Apr 04, 2022</div></div>					