

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 12/26/2024	APWS Task ID: 6886CC30CBDC403A860144C3EAD7D3AA	APWS Project ID: FF2FFAF3AF0E4B69973992D7965A191C
Procedure: FIX BIXER 10 AK US		Enroute: NO	Specialist: Patterson, Lawrence		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: AFS: 8260-2 REVISIONS. BIXER, AK REV 10; JIVUB, AK REV 2; OILEE, AK REV 6. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: DON LANIER, AJV-A441 MANAGER, 405-954-8282.</div> <div>QUALITY 18 CHECKED</div>					