

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 03/24/2022	APWS Task ID: 69C73109D2314DEA9BBFE44FEFD43511	APWS Project ID: A86F0E5B0EB641B0A57562AA98412EA1
Procedure: FIX ERNIE 8 SC US		Enroute: NO	Specialist: Teffeteller, David		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: ERNIE, SC REV 8 DICKINSON VORTAC, ND REV 14 CONTACT DAVE TEFFETELLER/240-457-1998</p>					

QUALITY
45
CHECKED

ESV Details

Originating Office :AJV-A45		Airspace Docket Number :		Request Type :Revision		
Facility Data						
Chart Name:ERNIE XING V311		City:COLLIERS		Ident:IRQ		State:SC
Type/Class: H-VOR		Frequency: M113.9		Reference Number: 21114120		
Extended Service Volume Data: (Original Record)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	
FAA 861939 - 037	93		59	25	150	
Requirement: 190326RAJV-A410 ERNIE XING V311 FIELD STRENGTH. PENDING FLIGHT INS FIFO ON 07/09/1987.			190328 APPROVED. FREQ. PROTECTION & FC BY THOMAS HERNDON ATL			
Signature:Gurney Rebecca		Routing Symbol:			Date:04/01/2019	
Extended Service Volume Data: (Requesting Officer)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	
FAA 861939 - 037	93		60	25	150	
Requirement: ERNIE XING V311						
Signature:Gurney Rebecca		Routing Symbol:AJV-A45			Date:11/10/2021	
Extended Service Volume Data: (FIFO)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	Action Type
FAA 861939 - 037	93					
Requirement/Remarks:						
Signature:		Routing Symbol:			Date:	