

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 11/05/2020	APWS Task ID: 70840ACEF62143C094A6A2DC3C0E00CF	APWS Project ID: 74D6D8A9F6D74D05AD01E34C02326802
Procedure: RNAV (GPS) RWY 33 AMDT 1A		Enroute: NO	Specialist: Roslewski, Russell		Agreement Number:
Airport ID: KGGF	Airport Name: GRANT MUNI		Airport City: GRANT		State: NE
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: P-NOTAM</div> <div>New circling areas evaluated, MDAs did not change.</div> <div>Processed IAW Aircraft Operations Group (AJF-10) Memo, April 29, 2020, Subject: Flight Inspection Review Not Required.</div> <div>Jason Kretschmer, 405-954-4019</div> <div><div>QUALITY 16 CHECKED</div><div>QUALITY 15 CHECKED</div></div>					



WAAS CH 62908 W33A	APP CRS 317°	Rwy Idg 4797 TDZE 3425 Apt Elev 3425
--	------------------------	---

OLD

RNAV (GPS) RWY 33
GRANT MUNI (GGF)

NA DME/DME RNP-0.3 NA. When local altimeter setting not received, use Ogallala altimeter setting and increase all DA/MDA 60 feet and LPV all Cats visibility 1/4 mile. VDP NA when using Ogallala altimeter setting.	MISSED APPROACH: Climb to 5600 direct AHUJ and hold.
--	--

DENVER CENTER 132.7 397.85	UNICOM 122.8 (CTAF) 0
--------------------------------------	---------------------------------



5600	AHUJ	AYOXOS	5 NM Holding Pattern
* LNAV only	FOMUK 3 NM to RW33	IYAYU	137° → 5600
RW33	* 1.2 NM to RW33	5200	← 317°
1.2 NM	1.8 NM	2.4 NM	6.1 NM
CATEGORY	A	B	C
LPV DA	3710-1	285 (300-1)	NA
LNAV MDA	3840-1	415 (500-1)	NA
CIRCLING	3900-1	3980-1	NA
	475 (500-1)	555 (600-1)	

KGGF
Grant Muni
Grant, NE
1:100k
Circling - all procedures

