

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 02/23/2023	APWS Task ID: 74DF6D87DE6E4C1A926E8A40B6B1FFAC	APWS Project ID: 74288887EEAC4540B008A2B938CF47D7
Procedure: FIX CLYER 2 OA US		Enroute: NO	Specialist: Thibodeaux, Charles		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: STANDALONE MULTIPLE FIXES PROJECT: CLYER FL, REV 2 WHYYT FL, REV 1 PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: JASON KRETSCHMER, AJV-A421 MANAGER, 405.954.4019</div> <div><div>Digitally signed by JASON KRETSCHMER Nov 28, 2022</div><div>J ZEDER 11/18/2022</div><div>QUALITY 16 CHECKED</div></div>					