



Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 04/20/2023	APWS Task ID: 7FD1B72A890E4A24866D1D4C2D832162	APWS Project ID: A70578A8759B4B70BFCF986228D62C53
Procedure: RNAV (GPS) RWY 23 AMDT 1A		Enroute: NO	Specialist: Cronk, Russell		Agreement Number:
Airport ID: KLCH		Airport City: LAKE CHARLES		State: LA	
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div> <div> Procedure Comments: P-NOTAM </div> <div>  12/6/22 J. DuBois </div> <div> OBSTACLE - CAUSES FINAL LNAV MDA TO BE RAISED 20 FT: 22-003281, 148 MSL TOWER, RAISED TO 158 MSL VIA 2021-ASW-3562-OE. (SAME OBST, ADJUSTED HEIGHT.) </div> <div> CANCELS T-NOTAM: !FDC 1/7032 LCH IAP LAKE CHARLES RGNL, LAKE CHARLES, LA. RNAV (GPS) RWY 23, AMDT 1... LNAV MDA 420/HAT 405 ALL CATS. 2103181912-2303181912EST </div> <div> PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. </div> <div> ACTIVE DATA USED. </div> <div> CONTACT DON SMITH 405-954-8222 OR MARK ADAMS 405-954-9946. </div> <div> <div>2/1844</div> <div>  </div> </div> </div>					

