

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 08/10/2023	APWS Task ID: 84C078C06EBE47A9863BF7450388F233	APWS Project ID: 3E63E74AA10A4568A0B65B7F5F71A377
Procedure: RNAV (GPS) RWY 5 AMDT 0E		Enroute: NO	Specialist: Dumar, Ralph		Agreement Number:
Airport ID: W40			Airport City: MOUNT OLIVE		State: NC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION</div> <div>AIRPORT PENDING DATA USED. REMARKS: LOCAL ALTIMETER SOURCE AND ALTERNATE MINIMUMS ADDED. CONTACT RAKE MCGRAW (405) 954-8711</div> <div>QUALITY 30 4/13 BBLUE CHECKED</div> <div>QUALITY 41 CHECKED</div>					

WAAS CH 69431 W05A	APP CRS 049°	Rwy Idg TDZE Apt Elev	5254 166 166
--	------------------------	-----------------------------	---



RNAV (GPS) RWY 5

MOUNT OLIVE MUNI (W40)

▼

NA

DME/DME RNP-0.3 NA. Rwy 5 helicopter visibility reduction below $\frac{3}{4}$ SM NA. Obtain Seymour-Johnson AFB altimeter setting on CTAF; when not received, use Duplin Co altimeter setting and increase LPV DA to 634 and all MDA 20 feet.

MISSED APPROACH: Climb to 900 then climbing right turn to 2000 direct WIKOG and hold.

AWOS-3 120.075	SEYMOUR JOHNSON APP CON* 119.7 273.6	UNICOM 122.8 (CTAF) 0
--------------------------	--	---------------------------------

